Wipe Out Enterprises Inc.

Work instructions

Document #WOEI 0064

Originator: Rick Eilerman

Approved Date:

Revision Level: Original

Revision Approval Date/ Revisers Initials:

PURPOSE: Instructions for Copper Exhaust Gasket

TOOLS/COMPONENTS:

INSTRUCTIONS:



1. Identify the TOP of the gasket by locating the stamped “T” designation



2. Glue both sides of the gasket with Permatex ULTRA BLACK or High Temp Glue
3. Torque exhaust bolts or studs and nuts to 80 ft/lbs

NOTE: Center holes may NOT be used depending on the cylinder head. *(Some cylinder heads and exhaust manifolds use center holes).* **Gasket will work on both set ups.**

